

Kissing Gate Project: Tiverton and Tilstone Fearnall

Footpath	Location	Reason	Priority
Tiverton 3	East end	Private gate looks a deterrent off the service road	2
Tiverton 4	SE end onto Townfield Lane	Stile on top of bank	1
Tiverton 4	GR544616	Broken stile needs replacing	1
Tiverton 5	South end onto Pudding Lane	Enhance attractive area (walkers 'layby' with bench and daffodils)	2
Tiverton 7	East end onto Crib Lane	Raise profile of path and persuade farmer to stop dumping animal feed immediately over stile	2
Tiverton 15	GR559608	Wooden stile in need of replacement	1
Tiverton 16	GR564610	Wooden stile in need of replacement	1
Tiverton 19/ Tilstone Fearnall 4	Parish boundary	Akward wooden stile needs replacing	2
Tiverton 20	GR552606	Replace old, narrow iron kissing gate	2
Tilstone Fearnall 3	West end	No proper stile out of farmyard, kissing gate will make path far more obvious	1
Tilstone Fearnall 4	East end	Stile on top of steep bank straight onto Tilstone Bank Lane	1